GNITION ACCESSO



BENDIX BREAKER ASSEMBLIES

Early S4, S6 Mags P/N 07-06305 (10-357173) with spring (current production) Ea. P/N 07-06306 (10-357174) without spring (current production) Ea.

All above breaker assemblies used on either Right or Left Magnetos. Late S4/S6 Mags, S200 Mags'



BENDIX MAGNETO GREASE

#10-27165 - Factory recommended lubricant for bearings in Bendix magnetos.

#10-391200 - For use on distributor block bushing. Provides proper shaft lubrication. 8 oz. canP/N 10-391200

REPLACEMENT COILS FOR CONTINENTAL ENGINES PER SERVICE BULLETIN NO. 637

TCM Ignition Systems has issued Service Bulletin No. 637 to retire from service certain older coils and rotating magnets. The Bulletin applies to many S-20, S-200, S-600, and S-1200 series magnetos as identified in this chart. Compliance with this Bulletin is required at the next 100 inspection, annual inspection, or progressive maintenance inspection, whichever comes first. Order by new coil part number.

Magneto Series	Old Coil P/N	Color	New Coil P/N	Color	Our Price
S-20	10-163172				
S-200	10-163209	Opaque Amber to Dark Purple	10-357165-1	Bright Red to Dark Red	
	10-160887				
S-1200	10-349271	Opaque Amber	10-391088-1	Blue to Olive Green to Black	



ALTERNATOR FILTER

Replacement part for existing alternator filters. Wire won't break at the case and its clamp is made from heavy gauge steel. Double the capacitance compared to OEM alternator filters. For stubborn alternator noise, this Alternator filter combined with the Eliminator (P/N 11-08055) can trap a wide frequency range of elec-tronic noise. Both of these filters have been thoroughly tested under a DO 160D and are FAA/PMA approved. P/N 11-08060



MAGNETO FILTER FAA APPROVED

Lone Star Aviation's Magneto filter (FEED THRU) (Fail Safe Design) attenuates both low and high frequencies of noise generated from bendix magneto

ignition systems. The firing of the aircraft spark plugs through the ignition systems harness can cause noise problems and interference to aircraft electronics such as audio panels, radio equipment, navigation equipment, instrumentation, and autopilot systems on board an aircraft. This filter has been used by avionics shops. OEM aircraft manufacturers. and FBO's, to attenuate and suppress pulsating noise generated by their aircraft's magneto systems. The magneto filter is FAA-PMA approved and is compatible with the bendix series S20, S21, S200, D3000, D4000 magneto.

Features: • 1000 VDC working voltage, 5000VDC break down voltage • Capacitance: .05 uf-self healing technology • Braided cable is shielded, silver plate over copper, supplied in 8 inch lengths • Heavy duty mounting clamp • Advanced feed through design • Temp. range: -35°C to +80°C • Max. current: 20 amps.......P/N 07-00713

BOGERT AVIATION GROMME STRETCHER TOOL



Using the Grommet Stretcher is 2-3x's faster when stretching grommets over fittings and plugs. Improves safety because grommets are continuous. Operating Instructions: 4 Simple Steps Saves time and frustration. Insert grommet over end of Grommet Stretching Tool. Squeeze handle to spread the grommet. Insert cable through grommet and release the squeeze on tool handle. Remove the grommet from tool by sliding grommet off the ends..... P/N 11-06946

GROUND TERMINAL KITS



For S-20 series mags. Kit No. 10-52306 (AN3105)

Reg. No.	Part No.	No. Req.	Description	
1	10-30299	1	NUT - Coupling (Ground Terminal)	
2	10-56507	1	CROMMET Assy.(Ground Terminal)	
3	10-3383	1	FERRULE - Inner (Ground Wire)	
4	10-25725	1	SLEEVE - Insulating (Ground Wire)	

5 4

For 20 series mags. Kit NoP/N 10-52305

Reg. No.	Part No.	No. Req.	Description	
1	10-37669	1 NUT - Coupling (Ground Termi		
2	10-7030	1	FERRULE - Outer (Ground Wire)	
3	10-7029	1	FERRULE - Inner (Ground Wire)	
4	10-37668	1	SLEEVE - Insulating (Ground Wire)	
5	2-155	1	WASHER - Ground Wire Contact	

I

TCM/BENDIX **IMPULSE COUPLINGS**

Part No. 10-40307 10-40309 10-40314 10-40315 Core charge applies

TCM/BENDIX			
CAM ASSEMBLI	ES		
Part No.	Price		
10-40166-6			
10-40167-4			
10-40167-6			
Core charge applies			
	CAM ASSEMBLII Part No. 10-40166-6 10-40167-4 10-40167-6		

SEE WEBSITE FOR MORE TCM PARTS!