



427 HILLCREST WAY • REDWOOD CITY • CALIFORNIA 94062 ■ (650) 369-1188 • Fax (650) 369-9988

MODEL 880

CONTINUING AIRWORTHINESS

The Model 880 requires a battery exchange on a minimum of two years. If the "AA" battery is used as the memory supply, it is recommended on an annual basis. If the aircraft's hot wire is used for the memory, no continuing airworthiness is required.