

MARVEL-SCHEBLER CARBURETORS

MARVEL-SCHEBLER NEW CARBURETORS



Note: Customer will need to provide core for overhaul in the event our supplier does not have cores available to overhaul.

Note: All Rebuilt & Overhauled Carb Purchases will be Charged an Additional Fee for Core.

PLEASE CHECK WITH AIRCRAFT SPRUCE ON AVAILABILITY OF CORES AT MARVEL-SCHEBLER.

Carb. Model No.	OEM Part No.	Our Part No.	Our Price	Tempest Carb. Model No.	OEM Part No.	Our Part No.	Our Price
MA-4SPA™	10-3678-12--F	08-06304	---	MA-4SPA™	10-3678-32--F	08-06305	---
MA-4-5™	10-3859-1--F	08-06327	---	MA-4-5™	10-3878--F	08-06306	---
MA-4-5™	10-4164-1--F	08-06307	---	MA-3PA™	10-4233--F	08-06328	---
MA-3SPA™	10-4240-1--F	08-06329	---	MA-4-5™	10-4404-1--F	08-06308	---
MA-4-5™	10-4893-1--F	08-06309	---	MA-3SPA™	10-4894-1--F	08-06311	---
MA-3SPA™	10-4895-1--F	08-06312	---	MA-4SPA™	10-4910-1--F	08-06332	---
MA-4SPA™	10-5009--F	08-06315	---	MA-4-5™	10-5034--F	08-06335	---
MA-4SPA™	10-6110-F	07-26829	---				
MA-3PA™	10-5050--F	08-06336	---	MA-4-5™	10-5054--F	08-06337	---
MA-3SPA™	10-5082--F	08-06338	---	MA-3PA™	10-5126--F	08-06339	---
MA-3PA™	10-5142--F	08-06340	---	MA-4-5™	10-5193--F	08-06341	---
MA-3A™	10-5199--F	08-06316	---	MA-4SPA™	10-5217--F	08-06317	---
HA-6™	10-5219--F	08-06342	---	MA-3PA™	10-5220--F	08-06343	---
HA-6™	10-5224--F	08-06344	---	HA-6™	10-5230--F	08-06345	---
HA-6™	10-5235--F	08-06346	---	HA-6™	10-5253--F	08-06347	---
HA-6™	10-5255--F	08-06348	---	MA-3PA™	10-5257--F	08-06349	---
MA-3PA™	10-5267--F	08-06353	---	HA-6™	10-5283--F	08-06354	---
MA-4-5™	10-5284--F	08-06356	---	MA-4-5™	10-5288--F	08-06357	---
HA-6™	10-6001--F	08-06358	---	HA-6™	10-6019--F	08-06359	---
MA-4-5	10-6035-11-F	07-26832	---				
MA-4-5™	10-6045--F	08-06366	---	MA-4-5™	10-6050--F	08-06368	---
MA-4-5™	10-6054--F	08-06369	---	MA-4-5™	10-6102--F	08-06370	---

MARVEL-SCHEBLER REBUILT & OVERHAULED CARBURETORS

Model Number	OEM Part No.	Rebuilt Part No.	Rebuilt Price	Overhaul Part No.	Overhaul Price
MA-4SPA™	10-3678-12	08-06325-1	---	08-06325	---
MA-4SPA™	10-3678-32	08-06326-1	---	08-06326	---
MA-4-5™	10-3859-1	08-06371-1	---	08-06371	---
MA-4-5™	10-3878	08-06372-1	---	08-06372	---
MA-4-5™	10-4164-1	08-06373-1	---	08-06373	---
MA-3PA™	10-4233	08-06374-1	---	08-06374	---
MA-4-5™	10-4404-1	08-06376-1	---	08-06376	---
MA-4-5™	10-4404	08-06375-1	---	08-06375	---
MA-4-5™	10-4893-1	08-06378-1	---	08-06378	---
MA-3SPA™	10-4894-1	08-06379-1	---	08-06379	---
MA-3SPA™	10-4895-1	08-06380-1	---	08-06380	---
MA-4SPA™	10-4910-1	08-06382-1	---	08-06382	---
MA-4SPA™	10-4910	08-06381-1	---	08-06381	---
MA-4SPA™	10-6110	07-26830	---	07-26831	---
MA-3A™	10-4953	08-06383-1	---	08-06383	---
MA-4SPA™	10-5009	08-06384-1	---	08-06384	---
MA-4-5™	10-5034	08-06385-1	---	08-06385	---
MA-3PA™	10-5050	08-06386-1	---	08-06386	---
MA-4-5™	10-5054	08-06387-1	---	08-06387	---
MA-3PA™	10-5126	08-06388-1	---	08-06388	---
MA-4-5™	10-5193	08-06390-1	---	08-06390	---
MA-3A™	10-5199	08-06391-1	---	08-06391	---
MA-4SPA™	10-5217	08-06392-1	---	08-06392	---
HA-6™	10-5219	08-06394-1	---	08-06394	---
MA-3PA™	10-5220	08-06395-1	---	08-06395	---
HA-6™	10-5224	08-06396-1	---	08-06396	---
HA-6™	10-5230	08-06397-1	---	08-06397	---
HA-6™	10-5235	08-06398-1	---	08-06398	---
HA-6™	10-5253	08-06399-1	---	08-06399	---
HA-6™	10-5255	08-06400-1	---	08-06400	---
MA-3PA™	10-5257	08-06401-1	---	08-06401	---
MA-3PA™	10-5267	08-06402-1	---	08-06402	---
HA-6™	10-5283	08-06403-1	---	08-06403	---
MA-4-5™	10-5284	08-06404-1	---	08-06404	---
MA-4-5™	10-5288	08-06405-1	---	08-06405	---
HA-6™	10-6001	08-06406-1	---	08-06406	---
HA-6™	10-6019	08-06407-1	---	08-06407	---
HA-6™	10-6030-1	08-06408-1	---	08-06408	---
MA-4-5™	10-6035-11	08-06409-1	---	08-06409	---
MA-4-5™	10-6054	08-06410-1	---	08-06410	---



MARVEL-SCHEBLER FLOAT KIT

A new float has been developed for the small MA series carburetors. The new floats are a solid blue epoxy material with a smooth skin.

Small P/N 08-06508

Large P/N 08-06510



THROTTLE SHAFT MINOR REPAIR KIT 778-1007-F

Tempest MSA throttle minor repair kit (778-1007--F). All parts contained in this kit are covered under FAA/PMA PQ0111NM and/or PQ1296CE.

P/N 08-06539