CESSNA FIBERGLASS REPLACEMENT PARTS

CESSNA 177/180/185/188


CESSNA FIBERGLASS REPLACEMENT PARTS FOR 177

What Makes These Composite Parts Such An Excellent Value?

- Stronger than factory originals with no weight increase.
- Stronger than factory originals with no weight increase.
- Easily repaired with locally available fiberglass kits if ever damaged.
 Exact replacements of original equipment means easy installation.
- Money back guarantee if not completely satisfied!

RUDDER & VERTICAL TOPS

Cessna fiberglass replacement parts for 177 rudder and vertical tops



Description	Part No.	Price
177 Rudder Top (All) (SA-1733009-2)	05-03841	
177 Vertical Top (All) (SA-1731009-4)	05-03840	

GEAR LEG FAIRINGS

Cessna fiberglass replacement parts for 177 gear leg fairing.



Description	Part No.	Price
177 Upper Gear Leg (All) RH (SA-1741005-44)	05-03846	
177 Upper Gear Leg (All) LH (SA-1741005-43)	05-03845	
177 Brake Fairings 1972-'74 RH (SA-0741634-14)	05-03848	
177 Brake Fairings 1972-'74 LH (SA-0741634-13)	05-03847	
177 Brake Fairings 1975&on RH (SA-1741027-2)	05-03849	
177 Brake Fairings 1975&on LH (SA-1741027-1)	05-03850	

CESSNA FIBERGLASS REPLACEMENT PARTS FOR 180/185

ELEVATORS & STABILIZERS

Here are some of our most popular items. These tips take a good deal of stress in just normal flying circumstances. They're also frequent victims of ramp rash. The original plastic simply can't stand up to the task as well as fiberglass replacements from Stene Aviation. Plus, if these parts ever do withstand damage, they're easily repaired

with stand damage, they're easily repaired with readily available fiberglass repair kits from your local automotive parts store

LH/RH Horizontal Tip (SA-0732613-1)......P/N 05-03779

GEAR LEG AND BRAKE FAIRINGS

These are excellent items for replacing worn plastic originals. Your fiberglass replacements will be more durable with an improved finish over the original plastics.



Description	Part No.	Price
180/185 Brake Fairing RH(SA-0741059-2)	05-03804	
180/185 Brake Fairing LH(SA-0741059-1)	05-03805	

180/185 CONT. STRUT CUFFS

Here's an unbeatable item for renovating your Cessna; a set of replacement strut cuffs. Order just one cuff to replace a damaged original, or get a set of four for a complete replacement.



Description	Part No.	Price
180 Strut Cuff Upper RH (SA-0723605-4)	05-03774	
180 Strut Cuff Upper LH (SA-0723605-3)	05-03773	
180 Strut Cuff Lower RH (SA-0723605-2)	05-03772	
180 Strut Cuff Lower LH (SA-0723605-1)	05-03771	

RUDDER & VERTICAL FIN CAPS

These parts are a snap to replace on most planes. Please note, indicate if you have a straight tail or a swept tail. It is also important to let us know if your fin cap needs to accommodate a strobe or beacon, and if so, if the light is front-mounted or center-mounted.



Description	Part No.	Price
180/182/188 Vertical Top No Beacon (SA-0731000-200)	05-03781	
180/182/188 Vertical Top Small Beacon (SA-0731019-1)	05-03782	
180/185 Vertical Top Small Beacon (SA-0731019-2)	05-03787	
185 Vertical Top No Beacon (SA-0742025-1)	05-03788	
180/182 Vertical Top Large Beacon (SA-0700031-2)	05-03789	
185 Vertical Top Large Beacon (SA-0731015-1)	05-03790	

WING & DORSAL TIPS

Wing tips are a common victim of hanger and ramp rash. Maybe you thought the plane was going to clear those doors as you wheeled it back into the hanger...the first indication that you were wrong was that grating sound as the wing tip met metal. Here's the solution: replacement fiberglass wing tips from Stene Aviation.



Description	Part No.	Price
180 Wing Tip (staight tip)- 1955-'67 (SA-0723615-200)	05-03797	
180/185 Wing Tip (small droop) 1969-'72 LH(SA-0523565-29)	05-03726	
180/185 Wing Tip (small droop) 1969-'72 RH(SA-0523565-30)	05-03727	
180/185 Wing Tip (small droop) 1973&on LH(SA-0723200-5)	05-03762	
172 RH Wing Tip (small droop) 1973&on (SA-0723200-6)	05-03764	

SEE WWW.AIRCRAFTSPRUCE.COM FOR COMPLETE LISTING